

FIG. 1




FIG. 3

IT0 glass photoresist applying 1st curing exposure mask developing 2nd curing etching(heating) finish




FIG. 2




FIG. 4